



Horizontal Pole




Step 1




Step 2


Vertical Pole




Step 3





Step 4



Step 5



Step 6




Step 7



Step 8

Horizontal Pole


Note : There are two kind of connectors.




Step 9

Step 10


Vertical Pole



Step 11




Step 12





Step 13


Step 14





Step 15




Step 16







Step 1



Step 2